PROPERTY INSPECTION REPORT FOR 277 Highland View Dr





Joel Rossmann AL # HI-4687 Bama Home Inspections IIc Inspection Address: 277 Highland View Dr Inspection Prepared For: John Smith Date of Inspection: 3/10/2025 Home Age: 4 Home Size: 1730 Weather: 40° Mostley cloudy

Report Introduction

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report if you have any questions. Remember, when the inspection is completed and the report is delivered, we are still available for any questions you may have.

Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFCI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

Video In Your Report –The inspector may have included videos of issues within the report. If you are opening the PDF version of the report make sure you are viewing the PDF in the free Adobe Reader PDF program. If you're viewing the report as a web page the videos will play in any browser. Click on any video within the report to start playing.

Throughout the report we utilize icons to make things easier to find and read. Use the legend below to understand each rating icon.



Acceptable – This item was inspected and is in acceptable condition for it's age and use.



Repair/Replace - Items with this rating should be examined by a professional and be repaired or replaced.



None - Items with this rating was not present during the inspection.



Monitor - Items with this rating should be monitored periodically to ensure that the issue hasn't become worse, warranting a repair or replacement.



Not Accessible - Items with this rating were not able to be fully inspected because access was blocked off or covered.

Our report contains a unique pop-up glossary feature. When you see words highlighted in yellow hover your mouse over the term. The definition or a tip about the item will appear!

Table Of Contents

Report Summary	4-5
Inspection Details	6
Den / Office	7-8
Master Bedroom	9-10
Bedroom 3	11-12
Bedroom 2	13-14
Master Bathroom	15-17
1/2 Bath	18-19
Bathroom 2	20-22
Kitchen	23-25
Laundry	26-27
Water Heater	28-29
Electrical	30-31
Roof	32-33
Attic 1	34-35
Foundation	36-37
Electrical	38
Fuel Source	39
Heat Pump	40
AC	41
Grounds	42-43
Home Exterior	44-45
Garage	46-47
	F





Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Bedroom 3		
Page 12 Item: 11	Ceiling Condition	 Small stains noted on the ceiling. They tested dry at the time of the inspection. Evidence of past leaking was noted. Water spot was tested by moisture meter, and read dry.
Bedroom 2	-	
Page 14 Item: 10	Window Condition	Window blocked by furniture.
Master Bathroom	-	
Page 15 Item: 2	Cabinets	Cabinet doors missing knobs or handles.
1/2 Bath	-	
Page 18 Item: 2	Cabinets	No knobs or handles on cabinet door.
Page 19 Item: 13	Toilets	Toilet seat cover loose; recommend tightening.
Bathroom 2	-	
Page 20 Item: 2	Cabinets	No knobs or handles on cabinet doors.
Page 21 Item: 17	Toilets	Toilet seat cover loose; recommend tightening.
Kitchen	-	
Page 23 Item: 1	Cabinets	 Cabinet doors missing knobs, consult with seller on repair/ replacement options. Drawer next to fridge crooked. Drawer next to refrigerator is crooked.
Page 25 Item: 18	Electrical	 Outlets under kitchen sink should be GFC in case of water contact. Refrigerator lite is not working.
Page 25 Item: 19	GFCI	 No GFCI protection present under kitchen sink, suggest installing GFCI protected receptacles for safety.
Laundry		
Page 26 Item: 5	Electrical	 GFCI outlets should be used in laundry room.
Page 26 Item: 6	GFCI	 The laundry receptacle should be GFCI protected type.
Electrical		
Page 30 Item: 1 Roof	Electrical Panel	Electrical panel should not have anything in front of it.
Page 32 Item: 6	Gutter	• Down spout on right side of house should extend at least 3 feet from home, so water does not seep into foundation.

Page 4 of 50

Attic 1		
Page 34 Item: 1	Access	Attic light located just inside access.
Page 35 Item: 4	Ventilation	 Soffit vent baffles should be bigger for proper ventalation in attic.
Page 35 Item: 7	Electrical	 Most areas not accessible due to insulation.
Electrical		
Page 38 Item: 1	Service Drop	 GFCI outlet on right side of house next to the A/C Unit not working properly.
Grounds		
Page 42 Item: 5	Vegetation	 Possible ant hill against house. Has a Pest Control Expert to evaluate.
Home Exterior		
Page 44 Item: 3	Siding Condition	 Bad patch job on rear right side of home.
Garage	_	
Page 46 Item: 1	Walls	Lip at front of garage. Possible trip hazard.

Inspection Details

1. Attendance	
	In Attendance: No other parties present at inspection.
2. Home Type	
	Home Type: Single Family Home
3. Occupancy	
	Occupancy: Occupied - Furnished • Access to some items such as: electrical outlets/receptacles, windows, wall/floor surfaces, and cabinet interiors may be restricted by furniture or personal belongings. Any such items are excluded from this inspection report.
4. Weather	
	49° Mostly cloudy

💾 Den / Office

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Location
Accept Monito None Repair/ No Replac Access
2. Ceiling Fans
Accept Monito None Repair/ No Replac Access · Operated normally when tested, at time of inspection.
3. Closets
Accept Monito None Repair/ No Replac Access Observations: • The closet is in serviceable condition.
4. Doors
Accept Monito None Repair/ No able r Replac Access
5. Electrical
Accept Monito None Repair/ No Replac Access • Some outlets not accessible due to furniture and or stored personal items.
6. Smoke Detectors
Accept Monito None Repair/ No able r Replac Access e
X
7. Window-Wall AC or Heat
Accept Monito None Repair/ No able r Replac Access e

Bama Home Inspections IIc

8. Ceiling Condition Accept Monito None Repair/ r Beplac Access e None Repair/ No Accept Monito r None Repair/ Access e Accept Monito r None Repair/ Access e Materials: There are drywall ceilings noted.


9. Wall Condition

Accept Monito None Repair/ No Replac Access e Materials: Drywall walls noted.



10. Window Condition

Accept Monito None Repair/ No able r Replac Access e





The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

1. Locations

Locations: Upstairs front of home.

Locations: Opstairs front of nome.
2. Cabinets
Accept Monito None Repair/ No able r Replac Access e
3. Ceiling Fans
Accept Monito None Repair/ No able r Replac Access Observations:
• Operated normally when tested, at time of inspection.
4. Closets
Accept Monito None Repair/ No Replac Access Observations:
X The closet is in serviceable condition.
5. Doors
Accept Monito None Repair/ No able r Replac Access e
6. Electrical
Accept Monito None Repair/ No able r Replac Access Observations:
• Some outlets not accessible due to furniture and or stored personal items.
7. Floor Condition
Accept Monito None Repair/ No Replac Access Flooring Types: Carpet is noted.
X
8. Smoke Detectors
Accept Monito None Repair/ No able r Replac Access e
X

Bama Home Inspections Ilc

	Condition None Repair/ Access Materia	als: Drywall walls noted.	
Х			
10. Wind	low Condition		
Accept Monito able r	None Repair/ No Replac Access Materia	als: Vinyl framed double hung window noted.	
Х			
11. Ceili	ng Condition		
	Nono Popair/ No	als: There are drywall ceilings noted.	


Page 10 of 50

Bedroom 3

1. Locations

Locations: Upstairs rear right side of home.

2. Cabinets





e

3. Ceiling Fans



Repair/ No Replac Access Observations:

Operated normally when tested, at time of inspection.

4. Closets

Accept Monito able r None Repair/ No Replac Access Observations: ė • The closet is in serviceable condition. Х


5. Doors



6. Electrical

Х


Accept Monito None able r Repair/ No Replac Access




7. Floor Condition

Accept Monito able r Repair/ e Flooring Types: Carpet is noted. None


8. Smoke Detectors






9. Wall Condition

Accept Monito None able r Repair/ e Materials: Drywall walls noted.






Water stain on ceiling. Check with moisture meter and area was dry.


Bedroom 2

1. Locations

Locations: Upstairs rear left.

2. Cabinets





Repair/ No Replac Access

e

3. Ceiling Fans



Observations: • Operated normally when tested, at time of inspection.

4. Closets

5. Doors



6. Electrical

Х

Х

Accept Monito None Repair/ No Replac Access Observations:


• Some outlets not accessible due to furniture and or stored personal items.

7. Floor Condition

Accept Monito None Repair/ No able r Replac Access

Repair/ Access Flooring Types: Carpet is noted.


8. Smoke Detectors







9. Wall Condition

Accept Monito None Repair/ No Access Materials: Drywall walls noted.









Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

1. Location

Locations: Upstairs in Master bedroom. 2. Cabinets Accept Monito able r None Repair/ No Replac Access Observations: Cabinet doors missing knobs or handles. Х 3. Ceiling Condition Accept Monito None able r Repair/ Access Materials: There are drywall ceilings noted. Х 4. Counters Accept Monito able r Repair/ No Replac Access None Observations: Solid Surface tops noted. Х 5. Doors Accept Monito able r None Repair/ No Observations: Replac Access No major system safety or function concerns noted at time of inspection. Х Electrical Accept Monito able r None Repair/ No Replac Access Х 7. GFCI None Accept Monito able r Repair/ No Replac Access Observations: GFCI in place and operational Х 8. Exhaust Fan Accept Monito able r Repair/ No Replac Access None Observations: The bath fan was operated and no issues were found. Х

9. Floor Condition
Accept Monito None Repair/ No able r Replac Access Materials: Floating laminate type flooring noted.
10. Heating
Accept Monito None Repair/ No Replac Access Observations:
• Central heating and cooling noted in this room. At the time of the inspection, all appeared to be functioning and in serviceable condition.
11. Plumbing Accept Monito None Repair/ No able r Replac Access
able r Replac Access e
12. Showers Accept Monito None Repair/ No
able r Replac Access
X
13. Shower Walls
Accept Monito None Repair/ No Obconventions:
Able r Replac Access Observations. e Fiberglass surround noted.
X
14. Bath Tubs
Accept Monito None Replar Access Observations:
15. Enclosure
Accept Monito None Repair/ No able r Replac Access
16. Sinks
Accept Monito None Repair/ No able r Replac Access
× ·
17. Toilets Accept Monito None Repair/ No Replac Access Observations:
able r Replac Access Observations:
X S

18. \	Winc	low (Cond	lition	
Accept able	Monito r	None	Repair/ Replac e	No Access	
		Х			

Bama Home Inspections IIc

277 Highland View Dr, Lincoln, Alabama

1/2	Bath
-----	------

1. Locations

Locations: Main floor off of kitchen.

2. Cabinets

Accept Monito None Repair/ No able r Replac Access Observations:

•	No	kno	bs	or	hand	les	on	ca	binet	d	00	r
				•.			••••					

3. Ceiling Condition

Accept Monito None Repair/ Access Replac Access Materials: There are drywall ceilings noted.



Х

4. Counters



5. Doors

able r	Observations: • No major system safety or function concerns noted at time of inspection.
X	• No major system salety of function concerns noted at time of inspection.

6. Electrical

Accept able r Monito None Repair/ No Access Observations:

-										
	 No ma 	jor sys	stem	safety	or function	concerns	noted	at time	of inspection.	


7. GFCI

Х



8. Exhaust Fan

Accept Monito None Repair/ No Replac Access Observations:




The bath fan was operated and no issues were found.

9. Floor Condition

Accept Monito None Repair/ No Replac Access Materials: Floating laminate type flooring noted.



10. Heating								
Accept Monito None Repair/ No Observations:								
• Central heating and cooling hoted in this room. At the time of the								
X inspection, all appeared to be functioning and in serviceable condition.								
11. Plumbing								
Accept Monito None Repair/ No								
able r Replac Access e								
12. Sinks								
Accept Monito None Repair/ No able r Replac Access								
13. Toilets								
Accept Monito None Renair/ No								
• Toilet seat cover loose; recommend tightening.								
Seat loose. Needs to be tightened.								
14. Window Condition								




Bathroom 2

1. Locations

Locations: Jack and Jill bathroom located upstairs between bedroom 2 and bedroom 3.

2. Cabinets



10. Heating Accept Monito None Repair/ No Replac Access Observations: able r Beplac Access Observations:
X Central heating and cooling noted in this room. At the time of the inspection, all appeared to be functioning and in serviceable condition.
11. Plumbing Accept Monito None Repair/ No Replac Access e
X
Accept Monito None Repair/ No able r None Repair/ Access Observations: • functional
13. Shower Walls
Accept Monito None Repair/ No Replac Access Observations:
14. Bath Tubs
Accept Monito None Repair/ No able r Replac Access Observations:
15. Enclosure
Accept Monito None Repair/ No Replac Access Observations:
16. Sinks
Accept Monito None Repair/ No able r Replac Access e
17. Toilets
Accept Monito None Repair/ No able r Replac Access Observations:
• Toilet seat cover loose; recommend tightening.



Toilet seat needs to be tightened.

18. Window Condition





The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

1. Cabinets

1. Cabinets
Accept Monito r None Repair/ No e Observations: • Cabinet doors missing knobs, consult with seller on repair/ replacement options. • Drawer next to fridge crooked. • Drawer next to refrigerator is crooked.
Cabinet drawer next to fridge is in crooked.
2. Counters
Accept Monito None Repair/ No able r Observations: • Solid Surface tops noted. • No discrepancies noted.
3. Dishwasher
Accept Monito None Repair/ No able r Beplac Access X Observations: Observations: • Dishwasher was operational at the time of inspection. Dishwashers most commonly fail internally at the pump, motor or seals. We do not disassemble these units to inspect these components. We recommend you operate this unit prior to closing.
4. Doors
Accept Monito None Repair/ No able r Replac Access e
5. Garbage Disposal

5. Garbage Disposal Accept Monito None Repair/ No Replac Access

Х

None Repair/ No Replac Access Observations:

• Operated - appeared functional at time of inspection.

6. Microwave
Accept Monito None Repair/ No able r Built-in microwave ovens are tested using normal operating controls. Unit Was tested and appeared to be serviceable at time of inspection. Leak and/or efficiency testing is beyond the scope of this inspection. If concerned, client should seek further review by qualified technician prior to closing.
7. Cook top condition
Accept Monito None Repair/ Replac No Observations: x -
8. Oven & Range
Accept Monito None Repair/ No r P Observations: Observations: Oven(s): Electric All heating elements operated when tested.
9. Sinks
Accept Monito None Repair/ No able r Beplac Access e • No deficiencies observed.
10. Trash Compactor
Accept Monito None Repair/ No r e X
11. Vent Condition
Accept Accept able None Repair/ No Repair/ No Replac Access Materials: Recirculating X
12. Window Condition
Accept Monito None Repair/ No able r Replac Access
13. Floor Condition
Accept Monito None Repair/ No Replac Access Materials: Floating laminate type flooring noted.
14. Plumbing
Accept Monito None Repair/ No able r Replac Access e

15. Ceiling Condition
Accept Monito None Repair/ No able r None Replac Access Materials: There are drywall ceilings noted.
16. Patio Doors
Accept Monito None Repair/ No able r Replac Access e
17. Screen Doors
Accept Monito None Repair/ No able r Replac Access e
18. Electrical
Accept Monito None Repair/ No Replac Access Observations:
X Outlets under kitchen sink should be GFCI in case of water contact. • Refrigerator lite is not working.
Outlets under kitchen sink need to be changed to Refrigerator light is out. a GFCI outlet.
19. GFCI
Accept Monito None Repair/ No Replac Access Observations: • GFCI in place and operational.
X • No GFCI protection present under kitchen sink, suggest installing GFCI protected receptacles for safety.
20. Wall Condition
Accept Monito None Repair/ No able r Beplac Access Materials: Drywall walls noted.
X


Bama Home Inspections IIc



1. Locations


Locations: Upstairs in Den/Office area.


2. Cabinets






3. Counters





4. Dryer Vent

Accept able	Monito r	None	Repair/ Replac	
			e	



5. Electrical

Accept Monito None Repair/ No Replac Access Observations:



• GFCI outlets should be used in laundry room.

6. GFCI


Accept Monito None Repair/ No Replac Access Observations:


• The laundry receptacle should be GFCI protected type.



Laudry room should have a GFCI outlet.

7. Exhaust Fan
Accept Monito None Repair/ No able r Replac Access e
8. Wash Basin
Accept Monito None Repair/ No able r Replac Access e
9. Floor Condition
Accept Monito None Repair/ No Replac Access Materials: Floating laminate type flooring noted.
10. Plumbing
Accept Monito None Repair/ No able r Replac Access e
X
11. Wall Condition
Accept Monito None Repair/ No Replac Access Materials: Drywall walls noted.
X
12. Ceiling Condition
Accept Monito None Repair/ No Replac Access Materials: There are drywall ceilings noted.
X
13. Doors
Accept Monito None Repair/ No able r Replac Access
X V
14. Window Condition
Accept Monito None Repair/ No able r Replac Access e








This report describes the amperage and voltage rating of the service, the location of the main disconnect and any sub panel(s), the presence of solid conductor aluminum branch circuit wiring, the presence or absence of smoke detectors and wiring methods. Inspectors are required to inspect the viewable portions of the service drop from the utility to the house, the service entrance conductors, cables and raceways, the service equipment and main disconnects, the service grounding, the interior components of the service panels and sub panels, the conductors, the over-current protection devices (fuses or breakers), ground fault circuit interrupters and a representative number of installed lighting fixtures, switches and receptacles. All issues or concerns listed in this Electrical section should be construed as current and a potential personal safety or fire hazard. Repairs should be a priority, and should be made by a qualified, licensed electrician.

1. Electrical Panel

Х



Repair/ No Location: Panel box located in garage.

- Observations:
 - No major system safety or function concerns noted at time of inspection at main panel box.
 - Main cutoff on rightside exterior of home.
 - Electrical panel should not have anything in front of it.



Main Electrical Shutoff.




Main Electrical shutoff






Items are not to be placed in front of Electrical panel.





Bama Home Inspections IIc	277 Highland View Dr,	Lincoln,	Alabam
Roof			
1. Roof Condition			
Accept Monito None Repair/ No able r Monito Access Materials: Visually accessible from grou Materials: Asphalt shingles noted. Observations: • No major system safety or function co		nspectior	۱.
2. Flashing			
Accept Monito None Repair/ No able r Replac Access e			
x			
3. Chimney			
Accept Monito None Repair/ No able r Replac Access e			
4. Sky Lights			
Accept Monito None Repair/ No able r Replac Access e			
5. Vent Caps			
Accept Monito None Repair/ No able r Replac Access			
X			
6. Gutter			
Accept Monito None Repair/ No able r Replac Access Observations:			
 No major system safety or function co Down spout on right side of house sho so water does not seep into foundation. 	ould extend at least 3 fee	•	

а



Front right side of home gutter spout should have an extension on it to prevent water from getting under the house.



This report describes the method used to inspect any accessible attics; and describes the insulation and vapor retarders used in unfinished spaces when readily accessible and the absence of insulation in unfinished spaces at conditioned surfaces. Inspectors are required to inspect insulation and vapor retarders in unfinished spaces when accessible and passive/mechanical ventilation of attic areas, if present.

1	1. A	cces	s			
	Accept Monito able r		None			Observations: • Pull Down Ladder located in:
	Х					 Attic light located just inside access.




2. Insulation Condition

Accept able	Monito r	None	Repair/ Replac e	No Access	Ma	
Х					De	

aterials: Blown in fiberglass insulation noted. epth: Insulation averages about 12-14 inches in depth



Bama Home Inspections IIc






This report describes the foundation, floor, wall, ceiling and roof structures and the method used to inspect any accessible under floor crawlspace areas. Inspectors inspect and probe the structural components of the home, including the foundation and framing, where deterioration is suspected or where clear indications of possible deterioration exist. Probing is not done when doing so will damage finished surfaces or when no deterioration is visible or presumed to exist. Inspectors are not required to offer an opinion as to the structural adequacy of any structural systems or components or provide architectural services or an engineering or structural analysis of any kind. Despite all efforts, it is impossible for a home inspection to provide any guaranty that the foundation, and the overall structure and structural elements of the building is sound.

1. Slab Foundation


Accept Monito None Repair/ No Replac Access Observations:

Х



2. Foundation Perimeter

Accept Monito None Repair/ No able r None Replac Access Observations:



• No deficiencies were observed at the visible portions of the structural components of the home.

3. Foundation Walls

Accept Monito None Repair/ No able r Replac Access Observations:




• No deficiencies were observed at the visible portions of the structural components of the home.

4. Cripple Walls




5. Ventilation

Accept Monito None Repair/ No able r None Replac Access e




6. Vent Screens






7. Access Panel

Accept Monito None Repair/ No able r Replac Access






Electrical					
1. S	ervic	e Dr	ор		
Accept able	Monito r	None	Repair/ Replac e	No Access	Amperage 200 Amp Unable to confirm due to Electrical is underground
		Х			Observations:
			•	-	 Located at Right side of Residence. GFCI outlet on right side of house next to the MC Unit not working properly.

Fuel Source

Х

Heat Pump







Located in attic.

Bama Home Inspections IIc

AC								
1. E	xteri	or						
Accept able	Monito r	None	Repair/ Replac e	No Access				
X								





A/C Unit shutoff.




Bama Home Inspections IIc



6. Hose Bib

Accept Monito None Repair/ No able r Replac Access Observations:					Observations: • Hose bib works
Х					Located on left side of house.
			•		 Located on right side of house.
					 Located at rear of house.




Home Exterior 1. Doors Accept Monito None Repair Access Observations:



• Corner Siding on right side rear of house is coming away from home. Have qualified person to check and fix.

2. Window Condition



3. Siding Condition







Corner siding pulling away from house. Qualified person to check and make recommendations.




Rear right side corner has a bad patch job done. Have a qualified person check and make recommendations.

4. Eaves & Facia






5. Exterior Paint



6. Stucco




7. Electrical

Accept able	Monito r	None	Repair/ Replac e	No Access
			Х	



Outlet box on right side of home next to A/C Unit will not reset (GFCI). Have an Electrician check, and replace.



7. Garage Door Condition
Accept Monito None Repair/ No Replac Access X
8. Garage Opener Status
Accept Monito None Repair/ No r Beplac Access Observations: X Chain drive opener noted.
9. Garage Door's Reverse Status
Accept Monito None Repair/ No e Observations: X
10. Floors

Materials: Poured concrete floor.

Dinning Room
1. Electrical
Accept Monito None Repair/ No able r Replac Access e
x
2. Windows
Accept Monito None Repair/ No able r Replac Access e
3. Ceiling
Accept Monito None Repair/ No able r Replac Access e
4. Walls
Accept Monito None Repair/ No able r Replac Access e
5. Floor
Accept Monito None Repair/ No able r Replac Access e
6. Cabinets
Accept Monito None Repair/ No able r Replac Access
7. Sliding Doors
Accept Monito None Repair/ No able r Replac Access

Family Room 1. Electrical Accept Monito None Repair/ No Benjac Access

abie		e	/1000000
X			



Light in front hallway should be raised. A tall person will hit it when walking by.

2. Windows Repair/ No Replac Access e Accept Monito None able r Х 3. Ceiling Accept Monito None able r Repair/ No Replac Access è Х 4. Walls Repair/ No Replac Access e Accept Monito None able r Х 5. Floor Accept Monito able r Repair/ No Replac Access None ė Х 6. Cabinets Accept Monito None able r Repair/ No Replac Access e Х



Glossary

Term	Definition
A/C	Abbreviation for air conditioner and air conditioning
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.
PVC	Polyvinyl chloride, which is used in the manufacture of white plastic pipe typically used for water supply lines.